

SERVICING & REPAIR PRICING

CAM REPAIRS

£12 INC vat [& p+p to UK only²]

WHATS INCLUDED:

Inspection¹, clean & lube, new trigger wires and new sling

TORQUE NUT RE-SLING

£4.50 INC vat [& p+p to UK only²]

WHATS INCLUDED:

Inspection¹ and new sling

Notes:

- > ¹If an item is deemed beyond economical repair a reduced rate replacement may be offered.
 - > ²For carriage charges and payment outside the UK please contact us.
 - > Payment can be made by Debit / Credit card or bank transfer; HSBC ac: 61737880 sort: 40-16-02
-
- 